Work Orde Monday, June 28							1					Page 1
Item ID: Revision ID:	D4021-1			Accept					Setup	Start		
	Handle Plate 6/28/2010 7/2/2010	Start Qty: 9.00 Req'd Qty: 9.00	1841 18 18 18 18 18 18 1		Cust Item I Customer:	D:				Stop		
Approvals:	Process Plan	n:	Date/16-6-28	Tooling: SPC (Y/N):		nte:	-	F	Run	Start Stop		
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr		sion Nbr					1					†
D4021 100 Waterjet FLOW CNC Waterjet 304 - () \$		Memo Cut as per Prog Rev: Dwg Rev:	dwg D4021	0.00				ß	10-	6-7°	В	(9)
110		Deburr as QC2- Inspect parts off	•	0.00			f 1					O
QC		Memo		0.00			(ir.	112-	96-d	₽	

0.00

Memo

Quality Control

	Dart	Aerosi	pace	Ltd
--	------	--------	------	-----

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRC	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							:			-
Part No		PAR #:								
	R	Resolution: QA: N/C Closed:				<u> </u>	Date:			
NCR:		\	WORK OR	DER NON-CONFORMA	ANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	on B	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
			Office Ling	Office Ling		Dute				
					i.					

Work Or	der	ID	601	83
---------	-----	----	-----	----

Monday, June 28, 2010 1:31:57 PM



Page 2

Item ID:

D4021-1

Accept



Setup Start

Stop



Revision ID: Item Name:

Handle Plate

Start Date:

Required Date: 7/2/2010

6/28/2010

Start Qty: 9.00

Req'd Qty: 9.00



Date: _____

Cust Item ID:

Customer:

Tool ID

Run

Start



Reference:

Approvals:

Process Plan:

QC:

Date:

Tooling:

0.00

SPC (Y/N):

Run Hours

Set Up/

Date:

Tool # Plan

Code

Date:

Stop

Reject

Qty



Insp.

Stamp

Sequence ID/ **Work Center ID**

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Memo

0.00

810/06/29

Accept

Qty

Reject

Number

140



Packaging

Packaging

Identify as per dwg & Stock Location: WA

0.00

0.00

150



Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/06/29 Ab

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHAI	NGES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Cty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,								
Part No	:	PAR #:	Fault Cat	egory:	NCI	R: Yes	No DQA	:	Date: _	
	R	esolution:	Dispositi	on:	QA	N/C CIG	sed:		Date: _	
NCR:			WORK ORI	DER NON-CONFOR	MANCE	(NCR)			
DATE	STEP	Description of NC			Section B		Verifica	tion	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	on	Sign & Date	Section		Chief Eng	QC Inspector
									,	
١.										
•										

Picklist Print

Monday, June 28, 2010 1:32:02 PM

Work Order ID: 60183

D4021-1 Parent Item:

Parent Item Name: Handle Plate

Start Date: 6/28/2010 Start Qty: 9.00

Required Date: 7/2/2010

Required Qty: 9.00

Comments:

IPP RevA: new issue DD 09.11.25 verified by:EC

per dwg REV.A DD 10.02.22 verified by:EC IPP Rev:C as per dwg revB

IPP Rev:B as

DD 10.04.20 verified by:EC

Component Item ID/	Replacemen
Item Name	Item ID

t Mfg/ Purch Item ID

Bin **Primary** Item Location Last Location Route Seq ID Unit of Qty on Measure Hand

Qty per Kit

Qty

Total

Issued

Qty

Date

Status Issued

Page 1

M304S11GA

Purchased

No

100

Loc Qty

132.4659

4.4659

128

sf 1

132.4659

0.1225

1.160526

1810-6-78

304/316 0.125 Sheet

Location MAT

114488 114799 Loc Code

114480

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	ES		1		
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			30.45					1 Tod Wigi	
Part No	•	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQA:	<u> </u>	Date: _	
	R	Resolution: Disposition: QA: N/C Closed:					Date: _		
NCR:	~	V	VORK ORI	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verificat	on	Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date			Chief Eng	QC Inspector
	-			- material de Company () de la company () de l					
				·					
		I .			ı	1		1	1

DART AEROSPACE LTD	Work Order:	40183
Description: Handle Plate	Part Number:	D4021-1
Inspection Dwg: D4021 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
5.13	+/-0.030	5,133	>			
0.75	+/-0.030	755	>			
2.25	+/-0.030	7.753	پ			
0.75	+/-0.030	.756	>			
0.125	+/-0.010	136	7			
, , , , , , , , , , , , , , , , , , ,				·		
			ļ			
			ļ			

	-					
						· · · · · · · · · · · · · · · · · · ·
A			 			


Measured by:	Audited by:	Preliminary Approval:
Date: (0-6-79)	Date: 10/06/05	Date:

Rev	Date	Change	Revised	3 Y∧	Approved
Α	10.06.08	New issue	KJ 9	X	AA
			1	<i>'</i> 7	,

Dart Aerospace Ltd	Da	ırt	Aer	osi	pace	Ltd
---------------------------	----	-----	-----	-----	------	-----


W/O:			WORK ORDER CHANGES												
DATE	STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
										· ·					
								•							
										:					
Part No:			PAR #:	Fault Category:NCI			R: Yes	No DQA	\:	Date:					
Resolution				Disposition: QA: N/C				N/C Closed: Date:							
NCR: WORK ORDER NON-CONFORMANCE (NCR)															
DATE	STEP	De	scription of NC	Corrective Action Section B			- Verification			Approval	Approval				
	0.2.		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector				
								:							
										,					
	į														
1															

[·] H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE




Dart Aerospace Ltd

W/O:										
DATE	STEP	PROC		Зу	Date	dty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									, is a mg.	
										!
								-		
Part No:		PAR #:	Fault Category: NO				No DQA:	Date:		
Resolution:			Disposition: Q			/C Clo	sed:	Date:		
NCR:			ORK OR	DER NON-CONFORMA	NCE (NCR)				
DATE	STEP	Description of NC	Corrective Action Section B			····	Verifica	ton	Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
								ł		
		·								
	:									



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE STEP		PROCEDURE CHANGE					Date	фy	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				Marin 1990 - 1990 - 1991 - 1700					T Too Wigi	
								İ		
								-		
		PAR #:	Fault Cate	lo DQA:		Date:				
		solution:	Disposition:				sed:	Date:		
NCR:			WORK ORD	ER NON-CONFORM	IANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Sect			verifica			Approval	Approvai
	J	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section		Chief Eng	QC Inspector
										1
									1	
10		10 10 10 10 10 10 10 10 10 10 10 10 10 1						<u> </u>		



Dart .	Aer-	osp	ace	Ltd
--------	------	-----	-----	-----

W/O:			V	ORK ORDER CHANGE	ES					
DATE	STEP	PROC	Ву	By Date		Cty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		PAR #:	_ Fault Ca	NCR: Ye	es No	DQA:	Date:			
		esolution:	on: Disposition: Q				ed:	Date:		
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (N	CR)				
DATE	STEP	Description of NC	Corrective Action Section B			Sign & Verifica				Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section	<u> </u>	Chief Eng	QC Inspector
					,					
										ļ
	1		1							